	Approved For Release 2002 0709 1717	PESK-09467RP06800280	JUBN TO GIA Library
	CLASSIFICATIONEMPL_T/300	THEL.	P. C.
COUNTRY	Germany (Servict Yone)	REPORT NO	
TOPIC	Altenburg Airfield		25X1A
EVALUATION	See balow PLACE OBTAINE	D	25X1A
1 DATE OF CO	NTENT	of Articular World William & Belleville Annual Annu	
DATE OBTAIN	VED.	ARED 2 January	1941
REFERENCES	S	25X1A	TO - TO STATE AND A SECURE OF THE SECURE AND A SECURE OF THE SECURE OF T
PAGES	2 ENCLOSURES (No. & TYPE) 1	- sketch on ditto	
REMARKS			
SOURCE		25X1X	
25X1X 1.	burg (E 51/K 27) airfield. (1) The only with courier planes. seen at the field. (2) The landing field, where a dredger w was being expanded toward the west. on a concrete taxiway 16 to 18 meter from the middle of the runway. (4) the former northern edge of the field northern section of the field was cowhere a clearing of about 60 hectare landing in the principal landing dir yet.	25X as removing piles of (3) Construction was wide which extended The entire road for downs graded. The downs graded. The downs graded. The stumps This was ection. The stumps	1B earth, apparently ork was being done d toward the hangars merly leading along tetour around the e edge of the woods, probably to facilita had not been removed
25X1X 3。 25X1B	Between noon and 4 p.m. on 18 Novemb type as previously seen were standin eastern edge of the field. The plan on an asphalt strip up to 200 meters Cloud base was low and there was occ field. Only three sentries were pos observation.	g in front of a clos es wore parked along wide in some spots, asional rain. Truck	the edge of the wood There was no flying
	Except for the laying of drainage pitwork was completed. (5) The old as by one third of its former length. The damage to the old section was being a length as the runway was constructed turntable was noticed at the souther equipment, such as mixing machines, and locomotives, boards and bear 60 dumpcars and four locomotives were tions.	phalt runway was exp he new section had a repaired. A new cem d parallel to it. I n end of the new tax narrow—gauge field ms were stored to be e used for the const	anded toward the nort cement surface and ent taxiway of the sa hat appeared to be a fiway. Construction railway tracks, dumpshipped away. "bout ruction of the instal
5.	On ℓ December, six twin-engine aircreoccupation of the field was unchanged	d.	ffs and landings. Th
Lo I	CLASSIFICATION CONTROL		AL 25X
	This document is hereby regraded to CONFIDENTIAL in accordance with the letter of 16 October 1978 from the Director of Central Intelligence to the Arc MARTON Reference 100 (108 : CIA-RE Next Review Date: 2008		25X

		Approved For Release 2002/08/08 : CIA-RDP82-0045/R006800280010-TIAL	
25X1		SWOR. T/CCNTROL/U	25X1A
	25X1A	Comments.	
25X1	25X1A		
	(3) 25X1A	its ground units. The landing field was enlarged toward the west in the summer of 1950. Small-scale grading work is possibly still being done. The information that the field is being enlarged toward the west is believed to be wrong.	- - 1
	ğ4)	This information has not been confirmed by other sources and is believed improbable. Another source reports in paragraph 4 that the construction work is completed.	- - - - - -
	(5)	For sketch of taxi- and rumways, see Annex. The sketch was drawn by the same source who made the sketch for a previous report.	25X1A
	•		

1 Annex: Southern End of Runway at the Altenburg Airfield.

CONFIDENTIAL

25X1